

PM7366 FREEDM-8

REVISION D AND E DEVICE ERRATA

Issue 7: November 2001

TABLE OF CONTENTS

1.	Introduction	3
1.1.	Device Identification	3
1.2.	Reference:.....	3
2.	FREEDM-8 Revision D & E Functional Deficiency List	4
2.1.	Offset underflow in Receive Packet Descriptor	5
2.2.	TDR Status Bits Not Reporting All Underflow Events.....	6
2.3.	PCI Hold Time Increased to 1ns.	7
2.4.	Two Channel, Asynchronous HSSI SYSCLK frequency.	8
2.5.	PCI bus fails to disconnect when multi-phase read extends beyond PCI address Space.....	9
3.	Documentation Errors	10


1. INTRODUCTION

In this document, Section 2 lists the known functional errata for Revision D and Revision E of PM7366 FREEDM-8 and Section 3 lists errors found in Issue 4 of the FREEDM-8 datasheet (PMC-970930).

1.1. Device Identification

The information contained in Section 2 relates to Revision D and Revision E of PM7366 FREEDM-8 only. The device revision code is marked at the end of the Wafer Batch Code on the face of the device (as shown in Figure 1.1). PM7366 FREEDM-8 is packaged in a 256-pin Ball Grid Array (BGA) package or a 272-pin Plastic Ball Grid Array (PBGA) package.

Figure 1.1: PM7366 FREEDM-8 Branding Format.



1.2. Reference:

- PMC-1970930, FREEDM-8 Long Form Data Sheet, Issue 4.

2. FREEDM-8 REVISION D & E FUNCTIONAL DEFICIENCY LIST

This section lists the known functional deficiencies for Revision D and Revision E of FREEDM-8 (as of the publication date of this document). For each deficiency, the known work-around and the operating constraints, with and without the work-around, are also described.

Please report any functional deficiencies not covered in this document to PMC-Sierra.

PMC-Sierra, Inc.
105-8555 Baxter Place
Burnaby, BC
Canada V5A 4V7

Tel: (604) 415-6000
App Support: (604) 415-4533
Fax: (604) 415-6001

Product information: info@pmc-sierra.com
Applications information: apps@pmc-sierra.com
Web Site: <http://www.pmc-sierra.com>

2.1. Offset underflow in Receive Packet Descriptor


Description:

When ALL of the following conditions are met:

1. The offset[1:0] field of a Receive Packet Descriptor (RPD) is non-zero.
2. The STRIP bit of register "**0x204 RHDL Indirect Channel Data Register #1**" is logic one.
3. The incoming packet payload is smaller than the FCS field (2 bytes for CRC-CCITT or 4 bytes for CRC-32).

The value in the "Bytes in Buffer [15:0]" field of the RPD can be underflowed. That is, this field will contain a negative value. If this field is interpreted as an unsigned integer, the content of the buffer can be erroneously interpreted as a very large number.

Figure 2.1: Receive Packet Descriptor.



Workarounds:

The following are **independent** workarounds for this error:

1. If the Offset[1:0] bits of RPD are set to zero, this problem will not occur.
2. If the STRIP field of "**0x204 RHDL Indirect Channel Data Register #1**" is set to zero, this problem will not occur.
3. If the buffer size is not larger than 32K Bytes, the most significant bit of the "Byte in Buffer" field can be used as a sign bit. The device software should discard RPDs that contain a negative "Bytes in Buffer" value.
4. For every RPD, the driver software can compare the "Bytes in Buffer[15:0]" field to ensure that it is smaller than or equal to "Receive Buffer Size[15:0]".

Performance with workaround:

FREEDM-8 works correctly.

Performance without workaround:

If the "Bytes in Buffer" field is interpreted as a very large number, the driver software may attempt to read data from outside of the allocated buffer space.

2.2. TDR Status Bits Not Reporting All Underflow Events.**Description:**

The underflow status bit (Status[2]) of Transmit Descriptor Reference (TDR) indicates whether or not an underflow condition is detected on the transmit packet¹.

In FREEDM-8 Rev D, the underflow status bit does NOT report ALL underflow events. That is, in some cases where underflow did occur, the underflow status bit would incorrectly return a value of zero ("0") to indicate that no underflow event was detected. On the other hand, when underflow did not occur this bit operates normally.

The total underflow count across all channels (register 0x508 PMON Transmit FIFO Underflow Count) is not affected by this and provides an accurate count.

Workarounds:

There is no workaround to this problem.

Performance with workaround:

Not applicable.

Performance without workaround:

The system will not be able to keep an accurate underflow count on a per HDLC channel basis.


¹ For additional information on the operation of Status[2] in a TDR, please refer to Fig. 9.14, Transmit Descriptor Reference of PMC-1970930 FREEDM-8 Datasheet.

2.3. PCI Hold Time Increased to 1ns.

Description:

PCI Input and Bi-directional signals require a minimum hold time ($t_{H_{PCI}}$) of 1 ns with respect to PCICLK.

Figure 2.2: PCI Interface Timing



Workarounds:

The PCI 2.1 specification requires PCI outputs to have a minimum 2 ns propagation delay. The clock skew between FREEDM-8 and other PCI devices in a system must therefore be kept below 1 ns to ensure correct operation.

Performance with workaround:

Operates normally.

Performance without workaround:

If the clock skew is not kept within the above limit, FREEDM-8 may operate incorrectly.

2.4. Two Channel, Asynchronous HSSI SYSCLK frequency.**Description:**

When a FREEDM-32, operating with a 33MHz SYSCLK, terminates two asynchronous HSSI links; if both links operate at their maximum 52 MHz Datarate, data corruption can occur.

Note that all other modes of operation, including two synchronous 52 MHz HSSI links, are error free.

Workarounds:

If two channel, asynchronous HSSI operation is desired, a 35 MHz SYSCLK reference clock should be used, rather than the 33 MHz SYSCLK specified in the datasheet.

Performance with workaround:

FREEDM-8 operates normally.

Performance without workaround:

If both asynchronous HSSI links operate at the maximum 52 MHz datarate, data corruption can occur.

2.5. PCI bus fails to disconnect when multi-phase read extends beyond PCI address Space.**Description:**

If a multi-phase read transaction on the PCI bus attempts to read a register address beyond the 4K addresses reserved for the FREEDM-8 registers, the FREEDM will not disconnect from the PCI bus causing it to hang.

Workarounds:

It is recommended that all read transactions, including multi-phase reads, remain within the 4K address range.

Performance with workaround:

The FREEDM-8 operates normally.

Performance without workaround:

If read operations extend beyond the reserved address space, the FREEDM-8 will not disconnect from the PCI bus.

3. DOCUMENTATION ERRORS

There are no known documentation errors in Issue 4 of PMC-970930 FREEDM-8 Datasheet (as of the publication date of this document).

Please report any documentation errors to PMC-Sierra.

PMC-Sierra, Inc.
105-8555 Baxter Place
Burnaby, BC
Canada V5A 4V7

Tel: (604) 415-6000
App Support: (604) 415-4533
Fax: (604) 415-6001

Product information: info@pmc-sierra.com
Applications information: apps@pmc-sierra.com
Web Site: <http://www.pmc-sierra.com>

NOTES

Seller will have no obligation or liability in respect of defects or damage caused by unauthorized use, mis-use, accident, external cause, installation error, or normal wear and tear. There are no warranties, representations or guarantees of any kind, either express or implied by law or custom, regarding the product or its performance, including those regarding quality, merchantability, fitness for purpose, condition, design, title, infringement of third-party rights, or conformance with sample. Seller shall not be responsible for any loss or damage of whatever nature resulting from the use of, or reliance upon, the information contained in this document. In no event will Seller be liable to Buyer or to any other party for loss of profits, loss of savings, or punitive, exemplary, incidental, consequential or special damages, even if Seller has knowledge of the possibility of such potential loss or damage and even if caused by Seller's negligence.

© 2001 PMC-Sierra, Inc.

PMC-1980452r7 ref PMC-1970930r4

Issue date: November, 2001.