



PIC16C717/770/771

PIC16C717/770/771 Rev. C Silicon/Data Sheet Errata

The PIC16C717/770/771 parts you have received conform functionally to the Device Data Sheet (DS41120B), except for the anomalies described below.

All problems listed here will be addressed in future revisions of the PIC16C717/770/771 silicon.

1. Module: A/D Converter

Exception to Table 15-12, Parameter A04.

PIC16C770/771 (12-bit A/D): No missing codes to 11-bits of resolution, up to 4 non-consecutive missing codes may occur when used to 12-bits of resolution.

Work around

None.

2. Module: Timer1

When Timer1 is configured to operate as an asynchronous counter, care must be taken that there is no incoming pulse while the module is being

turned off. If an incoming pulse arrives while Timer1 is being turned off (i.e., TMR1ON transitions from 1 to 0), the value of registers TMR1L and TMR1H will be unpredictable.

Work around

This solution involves changing Timer1 from Asynchronous to Synchronous mode before turning off Timer1. No additional resources are required for this solution.

Timer1 synchronization will start, effectively stopping Timer1, one Q period after the Synchronous mode is enabled, or one Q period later than would have been realized by simply clearing the TMR1ON bit. One additional count, in excess of the counts accrued during this extra Q period, may be accumulated before the TMR1ON bit is eventually cleared in the next instruction. The occurrence of this additional count is dependent on the phase relationship between OSC1, or the internal system clock, and T1CKI.

CODE EXAMPLE :

```
*****
; Call this routine to stop Timer1 asynchronous counting
;
; Timer1 is stopped after the timer is changed to synchronous mode
; The captured timer value resides in TMR1H and TMR1L at the completion of this
; routine.

TMR1Capture          ; entry point
    bcf    T1CON,NOT_T1SYNC ; set for synchronous mode
    bcf    T1CON,TMR1ON    ; stop timer
    bsf    T1CON,NOT_T1SYNC ; restore asynchronous mode
    return                ; return to calling routine
```

PIC16C717/770/771

3. Module: ECCP (Compare Mode)

The CCP1 output latch, observed on RB3/CCP1/P1A, can change unexpectedly when the ECCP module is changed from a set output on match (CCP1CON<3:0> = "1000") to clear output on match (CCP1CON<3:0> = "1001") or vice versa. This condition will occur, following an ECCP Reset, at the third iteration of the following sequence:

1. CCPR1<3:0> is changed from "1001" to "1000" or vice versa.
2. The TMR1H:TMR1L register pair matches the CCP1R1H:CCPR1L register pair.

Step 1 of the third iteration will cause the CCP1 output latch to immediately, and erroneously, change to the inverse of the CCPR1<0> bit. This gives the appearance of an inverted ECCP response to the third, and subsequent, compare match events.

The apparent inverted response will persist until the CCP1CON<3> bit is cleared (exiting Compare mode). Interrupts always occur correctly on the match condition. The error is only in the state of the CCP1 output latch.

Work around

Option 1

Use the ECCP toggle output on compare match mode (CCP1CON<3:0> = "0010").

Option 2

Do not selectively change the CCP1CON<0> bit. Instead, perform the following:

- Set the RB3 data latch to the same state as the CCP1 output latch (movf PORTB, f) to avoid an output glitch when the CCP1CON register is cleared.
- Next, clear the CCP1CON register (clrf CCP1CON).
- Finally, set the CCP1CON<3:0> bits to the next desired output on Compare Match mode.

TABLE 1: DC SPECIFICATION DEVIATIONS FROM DATA SHEET

Param No.	Sym.	Characteristic	Tested Specification			Data Sheet Specification			Units	
			Min	Typ	Max	Min	Typ	Max		
D005	VBOR	BOR Voltage	BORV<1:0> = 0100	2.35	—	2.80	2.5	—	2.66	V
			BORV<1:0> = 0101	2.55	—	3.02	2.7	—	2.86	V
			BORV<1:0> = 0110	3.95	—	4.71	4.2	—	4.46	V
			BORV<1:0> = 0111	4.23	—	5.05	4.5	—	4.78	V

TABLE 2: DC SPECIFICATION DEVIATIONS FROM DATA SHEET

Param No.	Sym.	Characteristic	Tested Specification			Data Sheet Specification			Units	
			Min	Typ	Max	Min	Typ	Max		
D420	VLVD	LVD Voltage	LVV<3:0> = 0100	2.35	—	2.80	2.5	—	2.66	V
			LVV<3:0> = 0101	2.55	—	3.02	2.7	—	2.86	V
			LVV<3:0> = 0110	2.64	—	3.14	2.8	—	2.98	V
			LVV<3:0> = 0111	2.83	—	3.37	3.0	—	3.2	V
			LVV<3:0> = 1000	3.11	—	3.71	3.3	—	3.52	V
			LVV<3:0> = 1001	3.29	—	3.93	3.5	—	3.72	V
			LVV<3:0> = 1010	3.39	—	4.04	3.6	—	3.84	V
			LVV<3:0> = 1011	3.58	—	4.26	3.8	—	4.04	V
			LVV<3:0> = 1100	3.77	—	4.49	4.0	—	4.26	V
			LVV<3:0> = 1101	3.95	—	4.71	4.2	—	4.46	V
			LVV<3:0> = 1110	4.23	—	5.05	4.5	—	4.78	V

Clarifications/Corrections to the Data Sheet:

In the Device Data Sheet (DS41120B), the following clarifications and corrections should be noted.

1. Module: DC Characteristics

Figure 15-1: TPIC16C717/770/771 VOLTAGE-FREQUENCY GRAPH, $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$;

Figure title changes from $+85^{\circ}\text{C}$ to **$+125^{\circ}\text{C}$** .

2. Module: DC Characteristics

Figure 15-3: PIC16LC717/770/771 VOLTAGE-FREQUENCY GRAPH, $-40^{\circ}\text{C} \leq T_A \leq 0^{\circ}\text{C}$, $+70^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$;

Figure title changes from $+85^{\circ}\text{C}$ to **$+125^{\circ}\text{C}$** .

PIC16C717/770/771

REVISION HISTORY

Rev A Document (2/01)

Original errata document.

Issues 1 (A/D Converter) and 2 (Timer1 Module) were added (page 1).

Item 1, Table 5-12 concerning Parameter A04, was added (page 2).

Rev B Document (9/01)

Issue 3 (ECCP Compare Mode), Table 1 and 2 were added (page 2).

Under the Clarifications/Corrections Section, Item 1, Table 15-12 was updated with additional information (page 3).

Under the Clarifications/Corrections Section, the following Items were added:

Item 2, Table 15-15 concerning DC Characteristics for PIC16C717 and PIC16LC717 was updated (page 4).

Item 3, Section 15.1 and Section 15.2 concerning DC Characteristics for PIC16C717/770/771 and PIC16LC717/770/771, respectively were replaced with a new Section, which contains updated information in a new format (page 5).

Item 4, Table 15-11 concerning DC Characteristics for VREF was replaced with updated information (page 8).

Rev C Document (8/02)

Under the Data Sheet Clarifications/Corrections Section, Items 1 through 4 were incorporated into DS41120B. New Items 1 and 2 were added for clarification.

Note the following details of the code protection feature on PICmicro® MCUs.

- The PICmicro family meets the specifications contained in the Microchip Data Sheet.
- Microchip believes that its family of PICmicro microcontrollers is one of the most secure products of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the PICmicro microcontroller in a manner outside the operating specifications contained in the data sheet. The person doing so may be engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable”.
- Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our product.

If you have any further questions about this matter, please contact the local sales office nearest to you.

Information contained in this publication regarding device applications and the like is intended through suggestion only and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. No representation or warranty is given and no liability is assumed by Microchip Technology Incorporated with respect to the accuracy or use of such information, or infringement of patents or other intellectual property rights arising from such use or otherwise. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, KEELOQ, MPLAB, PIC, PICmicro, PICSTART and PRO MATE are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, microID, MXDEV, MXLAB, PICMASTER, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.


dsPIC, dsPICDEM.net, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, microPort, Migratable Memory, MPASM, MPLIB, MPLINK, MPSIM, PICC, PICDEM, PICDEM.net, rPIC, Select Mode and Total Endurance are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

Serialized Quick Turn Programming (SQTP) is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2002, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.



Microchip received QS-9000 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona in July 1999 and Mountain View, California in March 2002. The Company's quality system processes and procedures are QS-9000 compliant for its PICmicro® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, non-volatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office

2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200 Fax: 480-792-7277
Technical Support: 480-792-7627
Web Address: <http://www.microchip.com>

Rocky Mountain

2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-692-7966 Fax: 480-792-4338

Atlanta

500 Sugar Mill Road, Suite 200B
Atlanta, GA 30350
Tel: 770-640-0034 Fax: 770-640-0307

Boston

2 Lan Drive, Suite 120
Westford, MA 01886
Tel: 978-692-3848 Fax: 978-692-3821

Chicago

333 Pierce Road, Suite 180
Itasca, IL 60143
Tel: 630-285-0071 Fax: 630-285-0075

Dallas

4570 Westgrove Drive, Suite 160
Addison, TX 75001
Tel: 972-818-7423 Fax: 972-818-2924

Detroit

Tri-Atria Office Building
32255 Northwestern Highway, Suite 190
Farmington Hills, MI 48334
Tel: 248-538-2250 Fax: 248-538-2260

Kokomo

2767 S. Albright Road
Kokomo, Indiana 46902
Tel: 765-864-8360 Fax: 765-864-8387

Los Angeles

18201 Von Karman, Suite 1090
Irvine, CA 92612
Tel: 949-263-1888 Fax: 949-263-1338

New York

150 Motor Parkway, Suite 202
Hauppauge, NY 11788
Tel: 631-273-5305 Fax: 631-273-5335

San Jose

Microchip Technology Inc.
2107 North First Street, Suite 590
San Jose, CA 95131
Tel: 408-436-7950 Fax: 408-436-7955

Toronto

6285 Northam Drive, Suite 108
Mississauga, Ontario L4V 1X5, Canada
Tel: 905-673-0699 Fax: 905-673-6509

ASIA/PACIFIC

Australia

Microchip Technology Australia Pty Ltd
Suite 22, 41 Rawson Street
Epping 2121, NSW
Australia
Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

China - Beijing

Microchip Technology Consulting (Shanghai)
Co., Ltd., Beijing Liaison Office
Unit 915
Bei Hai Wan Tai Bldg.
No. 6 Chaoyangmen Beidajie
Beijing, 100027, No. China
Tel: 86-10-85282100 Fax: 86-10-85282104

China - Chengdu

Microchip Technology Consulting (Shanghai)
Co., Ltd., Chengdu Liaison Office
Rm. 2401, 24th Floor,
Ming Xing Financial Tower
No. 88 TIDU Street
Chengdu 610016, China
Tel: 86-28-86766200 Fax: 86-28-86766599

China - Fuzhou

Microchip Technology Consulting (Shanghai)
Co., Ltd., Fuzhou Liaison Office
Unit 28F, World Trade Plaza
No. 71 Wusi Road
Fuzhou 350001, China
Tel: 86-591-7503506 Fax: 86-591-7503521

China - Shanghai

Microchip Technology Consulting (Shanghai)
Co., Ltd.
Room 701, Bldg. B
Far East International Plaza
No. 317 Xian Xia Road
Shanghai, 200051
Tel: 86-21-6275-5700 Fax: 86-21-6275-5060

China - Shenzhen

Microchip Technology Consulting (Shanghai)
Co., Ltd., Shenzhen Liaison Office
Rm. 1315, 13/F, Shenzhen Kerry Centre,
Renminnan Lu
Shenzhen 518001, China
Tel: 86-755-82350361 Fax: 86-755-82366086

China - Hong Kong SAR

Microchip Technology Hongkong Ltd.
Unit 901-6, Tower 2, Metroplaza
223 Hing Fong Road
Kwai Fong, N.T., Hong Kong
Tel: 852-2401-1200 Fax: 852-2401-3431

India

Microchip Technology Inc.
India Liaison Office
Divyasree Chambers
1 Floor, Wing A (A3/A4)
No. 11, O'Shaugnessey Road
Bangalore, 560 025, India
Tel: 91-80-2290061 Fax: 91-80-2290062

Japan

Microchip Technology Japan K.K.
Benex S-1 6F
3-18-20, Shinyokohama
Kohoku-Ku, Yokohama-shi
Kanagawa, 222-0033, Japan
Tel: 81-45-471-6166 Fax: 81-45-471-6122

Korea

Microchip Technology Korea
168-1, Youngbo Bldg. 3 Floor
Samsung-Dong, Kangnam-Ku
Seoul, Korea 135-882
Tel: 82-2-554-7200 Fax: 82-2-558-5934

Singapore

Microchip Technology Singapore Pte Ltd.
200 Middle Road
#07-02 Prime Centre
Singapore, 188980
Tel: 65-6334-8870 Fax: 65-6334-8850

Taiwan

Microchip Technology (Barbados) Inc.,
Taiwan Branch
11F-3, No. 207
Tung Hua North Road
Taipei, 105, Taiwan
Tel: 886-2-2717-7175 Fax: 886-2-2545-0139

EUROPE

Austria

Microchip Technology Austria GmbH
Durisolstrasse 2
A-4600 Wels
Austria
Tel: 43-7242-2244-399
Fax: 43-7242-2244-393

Denmark

Microchip Technology Nordic ApS
Regus Business Centre
Lautrup høj 1-3
Ballerup DK-2750 Denmark
Tel: 45 4420 9895 Fax: 45 4420 9910

France

Microchip Technology SARL
Parc d'Activite du Moulin de Massy
43 Rue du Saule Trapu
Batiment A - 1er Etage
91300 Massy, France
Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79

Germany

Microchip Technology GmbH
Steinheilstrasse 10
D-85737 Ismaning, Germany
Tel: 49-89-627-144 0 Fax: 49-89-627-144-44

Italy

Microchip Technology SRL
Centro Direzionale Colleoni
Palazzo Taurus 1 V. Le Colleoni 1
20041 Agrate Brianza
Milan, Italy
Tel: 39-039-65791-1 Fax: 39-039-6899883

United Kingdom

Microchip Ltd.
505 Eskdale Road
Winkersley Triangle
Wokingham
Berkshire, England RG41 5TU
Tel: 44 118 921 5869 Fax: 44-118 921-5820

08/01/02