

Installation Procedure for DuraSeal Splices and Terminals

1. Products:

DuraSeal Splice:

DS-XX-XX	D-406-XXXX
DS-MIXT-XX	

DuraSeal Terminal:

DB-X-XX	DP-X-XX	B-106-XX
DF-X-XX	DR-X-XX	DS-MIXT-XX

2. Application Equipment:

- Crimping tool: AD-1522
- Hot air gun:

Heat Gun	Reflector	Setting
HL1910E	PR-25 or PR-25D and HL1802E-ADAPT	6 on dial ⁽¹⁾
HL2010E		700°F on LCD ⁽¹⁾
CV-1981	PR-25D	7 ⁽¹⁾

3. Wire Preparation:

- Strip the stranded wire as shown.

Configuration		Product						
		Red		Blue		Yellow		
		Wire Range	Strip Length L (±0.5)	Wire Range	Strip Length L (±0.5)	Wire Range	Strip Length L (±0.5)	
Terminal		$0.5 < S_C < 1.0$	$L_C = 6$	$1.5 < S_C < 2.5$	$L_C = 6$	$3.0 < S_C < 6.0$	$L_C = 6$	see Fig. 1
Splice 1 to 1		$0.5 < S_C < 1.0$	$L_C = 7.5$	$1.5 < S_C < 2.5$	$L_C = 7$	$3.0 < S_C < 6.0$	$L_C = 8$	see Fig. 2
Splice 2 to 1	$\phi A < \phi B$	$1.5 < \phi A + \phi B < 3.7$ and $1.5 < \phi C < 3.7$	$L_A = 10$ $L_B = 7$	$2.0 < \phi A + \phi B < 4.3$ and $2.0 < \phi C < 4.3$	$L_A = 10$ $L_B = 7$	$3.0 < \phi A + \phi B < 6.4$ and $3.0 < \phi C < 6.4$	$L_A = 11$ $L_B = 8$	see Fig. 3
		$0.5 < S_A + S_B < 1.0$ and $0.5 < S_C < 1.0$		$1.5 < S_A + S_B < 2.5$ and $1.5 < S_C < 2.5$		$3.0 < S_A + S_B < 6.0$ and $3.0 < S_C < 6.0$		
	$\phi A = \phi B$	$1.5 < \phi A + \phi B < 3.7$ and $1.5 < \phi C < 3.7$	$L_A = 10$ $L_B = 10$	$2.0 < \phi A + \phi B < 4.3$ and $2.0 < \phi C < 4.3$	$L_A = 10$ $L_B = 10$	$3.0 < \phi A + \phi B < 6.4$ and $3.0 < \phi C < 6.4$	$L_A = 11$ $L_B = 11$	
		$0.5 < S_A + S_B < 1.0$ and $0.5 < S_C < 1.0$		$1.5 < S_A + S_B < 2.5$ and $1.5 < S_C < 2.5$		$3.0 < S_A + S_B < 6.0$ and $3.0 < S_C < 6.0$		

ϕA = diameter (mm) of the insulation of wire A.

S_C = cross section area (mm²) of wire C.





Fig. 3.






Fig. 4.




4. Installation Procedure:

- Select the correct DuraSeal crimp.
- Match its color with the color of the cavity of the crimp tool.
- Get the jaws in touch with the tubing.


DuraSeal Splice




DuraSeal Terminal



- Insert the stripped wire until it butts inside the DuraSeal crimp.
- Crimp the wire in place.
- Repeat the operation symmetrically for the DuraSeal splice.
- Allow the hot air gun to warm up.
- Position the DuraSeal crimp in the reflector (R).
- Apply heat to shrink the sleeve until the adhesive melt and flow around the extremities of sleeve.



Note: For DuraSeal terminals, in order to achieve maximum sealing (except for DuraSeal push-on) heat the terminal at 3 and press the flat part with a pair of pliers until the assembly cools.



Note: Do not heat the terminal for the push-on terminal.
Do not bend the splice or the terminal assemblies until they have completely cooled.

5. Inspection of Assembly:

Check:

- Wire insulation is positioned inside the DuraSeal sleeve.
- Adhesive has flowed to form a fillet around the ends of the sleeve.
- Sleeve is completely shrunk on to the wire insulation.
- Sleeve is not cut, split or discolored.
- Wire insulation has no signs of mechanical damage or overheating.

¹ These values are for reference only and may change based on other variables (i.e. reflector type, sleeve's relative distance to the reflector, etc.)

DISCLAIMER

All of the above information, including illustrations, is believed to be reliable. Users, however, should independently evaluate the suitability of each product for their application. Tyco Electronics makes no warranties as to the accuracy or completeness of the information, and disclaims any liability regarding its use. Tyco Electronics' only obligations are those in the Standard Terms and Conditions of Sale for this product, and in no case will Tyco Electronics be liable for any incidental, indirect, or consequential damages arising from the sale, resale, use or misuse of the product.