

PM5310

TBS DEVICE DRIVER

DEVICE DRIVER RELEASE NOTES

PROPRIETARY AND CONFIDENTIAL

RELEASE

ISSUE 2: NOVEMBER, 01

LEGAL INFORMATION

Copyright

© 2001 PMC-Sierra, Inc. All rights reserved.

The information is proprietary and confidential to PMC-Sierra, Inc., and for its customers' internal use. In any event, you cannot reproduce any part of this document, in any form, without the express written consent of PMC-Sierra, Inc.

PMC-2001252 (R2)

Disclaimer

None of the information contained in this document constitutes an express or implied warranty by PMC-Sierra, Inc. as to the sufficiency, fitness or suitability for a particular purpose of any such information or the fitness, or suitability for a particular purpose, merchantability, performance, compatibility with other parts or systems, of any of the products of PMC-Sierra, Inc., or any portion thereof, referred to in this document. PMC-Sierra, Inc. expressly disclaims all representations and warranties of any kind regarding the contents or use of the information, including, but not limited to, express and implied warranties of accuracy, completeness, merchantability, fitness for a particular use, or non-infringement.

In no event will PMC-Sierra, Inc. be liable for any direct, indirect, special, incidental or consequential damages, including, but not limited to, lost profits, lost business or lost data resulting from any use of or reliance upon the information, whether or not PMC-Sierra, Inc. has been advised of the possibility of such damage.

Contacting PMC-Sierra

PMC-Sierra
8555 Baxter Place
Burnaby, BC Canada V5A 4V7

Tel: +1-604-415-6000
Fax: +1-604-415-6200

Document Information: document@pmc-sierra.com
Corporate Information: info@pmc-sierra.com
Technical Support: apps@pmc-sierra.com
Web Site: <http://www.pmc-sierra.com>

REVISION HISTORY

Issue No.	Issue Date	Details of Change
1	October 16, 2000	Document created
2	November 2001	Document the software code changes since beta release

1 ABOUT THIS RELEASE

This is the rel-1.0 production release of the PM5310 (TBS) device driver. Rel-1.0 is intended for use with PM5310 TBS devices, revision A, B, C and the latest D. The rel-1.0 release is functionally complete and has been tested by PMC-Sierra as described in Section 3 below.

2 WHAT'S INCLUDED IN THIS RELEASE

This rel-1.0 release of the TBS driver includes the following files:

Directory	Filename	File Version
/src	tbs_api.c	1.64
	tbs_hw.c	1.28
	tbs_isr.c	1.20
	tbs_rtos.c	1.12
	tbs_util.c	1.28
/inc	tbs_api.h	1.15
	tbs_defs.h	1.27
	tbs_err.h	1.9
	tbs_fns.h	1.9
	tbs_hw.h	1.17
	tbs_rtos.h	1.9
	tbs_strs.h	1.25
	tbs_typs.h	1.10
/example	tbs_app.c	1.5
	tbs_debug.c	1.20
	tbs_debug.h	1.7
/	Makefile	1.15
/	software.lic	n/a
/	tbs_relnotes_r2.pdf (this file)	n/a

3 INSTALLATION

Please perform the following steps to install the PM5310 (TBS) device driver in your system.

- Unzip the release zip file, and install the files and its directory structure under your local drive. Modify the directory variable names in the `Makefile`, if necessary, to reflect your actual driver and directory names.
- Modify `tbs_typs.h`, `tbs_hw.h` and `tbs_rtos.h` as per your system's characteristics. Also, modify/implement the hardware and RTOS dependent functions in `tbs_hw.c` and `tbs_rtos.c`. Please refer to Section 8 of the TBS driver manual (PMC-2001251, Issue 3), Porting the TBS driver, for detailed instructions on porting the driver to your specific environment.
- Set up compile switches or other environment variables in the `Makefile`. Please refer to the `Makefile` for a detailed description of the available compile switches.
- Compile the source files and build the TBS driver using your make utility.
- Link the TBS driver to your application code.

4 TESTING STATUS OF THIS RELEASE

All TBS device driver Application Programming Interface (API) functions have been tested in-house using the PM5310 on a proprietary PMC-Sierra, Inc. application platform running VxWorks™ RTOS. As of the publication date of this document, there are no known bugs in this release. However, the customer is advised to consult our web site (<http://www.pmc-sierra.com>) for any relevant errata that may have been issued subsequent to the publication of this document.

5 WHAT'S NEW IN THIS RELEASE?

rel-1.0: Production release for the PM5310 device driver.

- The B1/E1 monitor status bits have been removed.
- For the latest TBS device, blocks RWTI, RPTI and RATI (82h, 92h, and A2h) do not have correct default values at power-up. APIs `tbsInit()` and `tbsReset()` write the correct value (2h) to those blocks to ensure proper operation.