



**September 11, 2006**

**Errata Document for CY7C65620/30, EZ-USB HX2LP™ Low-Power USB 2.0 Hub Controller Family**

This document describes the errata for the EZ-USB HX2LP™ Low-Power USB 2.0 Hub Controller Family, CY7C65620/30. Details include errata trigger conditions, scope of impact, available workarounds, and silicon revision applicability. Compare this document to the device's data sheet for a complete functional description.

Contact your local Cypress Sales Representative if you have HX2LP questions.

**Part Numbers Affected**

Part Number	Device Characteristics
CY7C65620	All Packages
CY7C65630	All Packages

**HX2LP Qualification Status**

Product status: Sampling

**HX2LP Errata Summary**

No errata items.

**References**

[1] Document # 38-08037, CY7C656XX EZ-USB HX2LPTM Low-Power USB 2.0 HUB Controller Family



**Document History Page**

<b>Document Title: EZ-USB HX2LP™ Low-Power USB 2.0 Hub Controller Family</b> <b>Document Number: 001-099068 Rev. **</b>				
<b>REV.</b>	<b>ECN NO.</b>	<b>Issue Date</b>	<b>Orig. of Change</b>	<b>Description of Change</b>
**	501609	See ECN	KKU	Original release of spec