


[Back](#)

<p>Use and Features :</p> <p>Weigh the weight of jewelleries Automatic Zero Resetting Automatic Swich off OverLoad and Low Battery Indicator</p>	
<p>1. Capacity</p>	<p>50g/100g</p>
<p>2. Division</p>	<p>0.1g/0.2g</p>
<p>3. Display</p>	<p>LCD Display, 4digits</p>
<p>4. Precision</p>	<p>±0.1g/0.2g</p>
<p>5. Operation Temperature</p>	<p>0-40°C</p>
<p>6. Safe Overload</p>	<p>100%F. S</p>
<p>7. power</p>	<p>4 pcs of GPA76 batteries</p>
<p>8. Center Warp</p>	<p></p>
<p>9. Table-board Size</p>	<p>100mm (L) *80mm (W)</p>
<p>10. Table-board Material</p>	<p>plastic</p>