

| MATERIALS | |
|--------------|-----------------------------|
| BODY | STAINLESS STEEL GOLD PLATED |
| CONTACT | GOLD PLATED |
| INSULATOR | PTFE |
| COUPLING NUT | BRASS NICKEL PLATED |

w.DataSheet4U.cor





ASSEMBLY PROCEDURES

- 1. STRIP CABLE AS SHOWN & TIN CENTER CONDUCTOR. DO NOT NICK CENTER CONDUCTOR.
- 2. SOLDER CONTACT TO CENTER CONDUCTOR.
- 3. INSERT CABLE INTO BODY UNTIL IT BOTOMS OUT. SOLDER OUTER CONDUCTOR TO BODY.



FSCM NO. 53919

PASTERNACK ENTERPRISES, INC.

P.O BOX 16759, IRVINE, CA 92623 PHONE (949) 261-1920 FAX (949) 261-7451

WEB ADDRESS: www.pasternack.com E-MAIL ADDRESS: sales@pasternack.≨om

COAXIAL & FIBER OPTICS

.com

PE4005

S. SMA MALE, SOLDER ATTACHMENT F

CAD FILE 080409 SCALE N/A SIZE 4 127

REV. A

- 1. UNLESS OTHERWISE SPECIFIED ALL DIMENSIONS ARE NOMINAL.
- 2. ALL SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE AT ANY TIME.
- 3. DIMENSIONS ARE IN INCHES.
- 4. FITS MIL-C-17 AND EQUIVALENT CABLES.