


DIN 47295, Type A
 Screw-on Version with Coupling Nut


DIN 47295, Form A
 Schraubverbindung mit Überwurfmutter

Straight Plug, crimp
Stecker gerade, crimp


Part Number	Cable Group	Assembly Instruction	Crimp-Insert	Remarks	Packing Unit
88 S 105-102 H3	02	88 O2	11 W 150-502	–	100
88 S 105-109 H3	09	88 O2	11 W 150-509	–	100
➤ 88 S 105-140 H3	40	88 O2	11 W 150-504	–	100
➤ 88 S 105-141 H3	41	88 O2	11 W 150-506	–	100
88 S 105-142 H3	42	88 O2	11 W 150-509	–	100
88 S 105-148 H3	48	88 O2	11 W 150-509	–	100
88 S 105-1V2 H3	V2	88 O2	11 W 150-550	–	100
88 S 105-1V4 H3	V4	88 O2	11 W 150-550	–	100
88 S 105-1V6 H3	V6	88 O2	11 W 150-504	–	100


Right Angle Plug, solder crimp
Winkelstecker, löt-crimp

Part Number	Cable Group	Assembly Instruction	Crimp-Insert	Remarks	Packing Unit
88 S 203-302 H3	02	88 P	11 W 150-102	–	100
➤ 88 S 203-340 H3	40	88 P	11 W 150-104	–	100
➤ 88 S 203-341 H3	41	88 P	11 W 150-106	–	100
88 S 203-342 H3	42	88 P	11 W 150-109	–	100
88 S 203-348 H3	48	88 P	11 W 150-109	–	100
88 S 203-3V2 H3	V2	88 P	11 W 150-150	–	100
88 S 203-3V4 H3	V4	88 P	11 W 150-150	–	100
88 S 203-3V6 H3	V6	88 P	11 W 150-104	–	100


Straight Plug, Q-Grip
Stecker gerade, Q-Grip

Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
88 S 10P-0S3 H3	R1-T2.0Li-75K	88 A5	–	100


Right Angle Plug, Q-Grip
Winkelstecker, Q-Grip

Part Number	Cable Group	Assembly Instruction	Remarks	Packing Unit
88 S 20P-009 H3	R1-T3.7Li-75K	88 A3	–	100
88 S 20P-0V6 H3	TZC 75024	88 A4	–	100

