

義隆電子股份有限公司 ELAN MICROELECTRONICS CORP.

HSIN-CHU: NO. 12, INNOVATION 1ST. RD.,

SCIENCE-BASED INDUSTRIAL PARK, HSIN-CHU CITY, TAIWAN, R.O.C.

TEL: 886-3-5639977 FAX: 886-3-5639966

Application Notes on

TITLE: EM55S Series Vo can't connect LED

Document Number: AP-EM55S-0003E


Date of Issue: 1 March 2002

Issue Version: 1.0

Supported Chips: All EM5500S Series chips

Applicable Software:

We found that some users connect an LED or Lamp to Vcc at Vo or Vo1 pin or as shown in the figure below:



Such connection is dangerous!

Because the EM55S Series will enter into Test mode when Vo Pin is at High during Power ON reset.

Test mode is only used for factory in-house chip testing purposes.

(Refer to the Note on the EM5500S Spec, pages 4~7)

Please do NOT use the above method of application circuit.

The function cannot perform emulation on the EM55S kernel chip.