



Male Connectors



Termination	Terminal	Shell Style	Cavities with Pre-mating Contacts	Contact Loading Pattern	Ordering Code
	Solder	H1 (11 way)		11 way fully loaded	CDR7H1M11RS3M
		H1 (11 way)	32	11 way fully loaded	CDR7H1M11RS3M-32E
		H1 (11 way)	2 & 32	11 way fully loaded	CDR7H1M11RS3M-2E32
		H2 (15 way)	Z32	15 way fully loaded	CDR7H2M15RS2M-32Z
	Solder	H2 (15 way)	Z32	15 way fully loaded	CDR7H2M15RS2M-32Z
		H2 (15 way)	Z4 & Z32	15 way fully loaded	CDR7H2M15RS2M-4Z32